

Compliance with this bulletin is

# **MANDATORY**

## **EFFECTIVE DATE**

30.07.21

## **APPLICABILITY**

This service bulletin is applicable for all Tercel's gyrocopter.

## **SUBJECT**

Bowden flexible cable holder replacement.

## **BACKGROUND**

Case was found during planned and obligatory inspection.

## **RISK OF NEGLECT**

Failure to comply with this instruction/information will result in

- possible damage of the aircraft,
- loss of rotor head control.

## **REQUIREMENTS**

Task may only be performed by an organization or individual according to service manual.

**PROCEDURES**

- 1) Check the holder in gyrocopter. Holder to be replaced is shown on pictures below [Fig. 1] and [Fig. 2].




Fig. 1




Fig. 2

The new, improved holder requires drilling additional, 22 mm deep M6 threaded hole in the rotorhead holder shown on [Fig. 3].




Fig. 3

Mounting of the new, improved holder is shown on following figures: [Fig. 4] and [Fig. 5]



Fig. 4



Fig. 5

	<b>SERVICE BULLETIN</b>	30-07-21
		No. 01-21

There are two main differences between these holders: the new one has reinforcing rib and additional hole.

**Holders without reinforced rib and additional hole have to be immediately replaced.**

- 2) There is no need to implement this bulletin If the gyrocopter has the new holder with reinforcing rib.
- 3) In case of an holder without rib and additional hole, please check it before and after every flight.  
**If any crack or permanent deformations are found, the gyrocopter can not be operated!**
- 4) If the gyrocopter has holder without reinforcing rib and additional hole please immediately contact with manufacturer Aviation Artur Trendak for further information: service manual and spare parts.

**People to contact:**

Michał Trendak  
[michal@trendak.eu](mailto:michal@trendak.eu)  
+48 606 347 080

Mateusz Piórkowski  
[mateusz@trendak.eu](mailto:mateusz@trendak.eu)  
+48 793 025 215