

| | | |
|--------------------------------------|-------------------------|------------|
| AVIATION Artur Trendak and Son | SERVICE BULLETIN | 18.07.2016 |
| | | No. 16-01 |

Compliance with this bulletin is

MANDATORY

SUBJECT: ENGINE SUPPORT INSPECTION

REASON: Inspection of engine support before and after every flight.

GYROCOPTERS AFFECTED: with serial number listed table 1; with installed engine mount on service works between October of 2015 and July 2016 or kept in stock;

| S/N of gyrocopters affected with this bulletin | |
|---|-------------|
| T&S G20815S | T&S J21715S |
| T&S J21315S | T&S J21815S |
| T&S J21415S | T&S J21915S |
| T&S J21515S | T&S J22015S |
| T&S J21615S | T&S J21215S |

Table 1

COMPLIANCE: IMMEDIATE


PUBLICATIONS AFFECTED:

- ✓ AMM Aircraft Maintenance Manual

| | | |
|--------------------------------------|-------------------------|------------|
| AVIATION Artur Trendak and Son | SERVICE BULLETIN | 18.07.2016 |
| | | No. 16-01 |

COMPLIANCE INSTRUCTIONS:

1. Before and after every flight inspect Engine Mount for cracks or other deformations. If detected the gyrocopter must be grounded, contact the manufacturer to specify the way to restore airworthiness.



2. Record for compliance with this bulletin in Gyrocopter logbook and contact manufacturer for further instructions.